

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2023

Submitted Date:

04/06/2023

Document Number:

707800267

FIELD INSPECTION FORM

Loc ID 424294 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
7 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10759
 Name of Operator: ORGANIC ENERGY COMPANY LLC
 Address: 1318 SMEDE HWY (HWY 92)
 City: BROUSSARD State: LA Zip: 70518

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Bienvenu, Benjamin	281-300-5049	ben@organicenergyco.com	
Fischer, Alex		alex.fischer@state.co.us	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424295	WELL	PR	03/02/2012	OW	081-07666	ELLGEN 11-10-1	PR

General Comment:

On Wednesday 4/5/2023, I, Inspector Scott Ramsey and Kris Neidel, conducted a joint OGI camera inspection at Organic Energy Ellgen 11-10-1, at Location # 424294 in Moffatt county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

Wind was light and temperature was around 30 degrees. We observed a line heater next to the vertical heated separator. Both heaters were running. ECD was running with slight heat trace observed with OGI camera.

During this inspection the following possible compliance issues were observed:

1. Some areas of location show signs of lack of stabilization and and no evidence of tracking BMP's.
2. Random staining from previous inspection around well head still present therefore C/A date remains the same 11/14/2022.
3. Stored equipment (tubing) from previous inspection is still present therefore C/A date remains the same 11/14/2022.

Refer to photograph of observed compliance issue.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored equipment (tubing) from previous inspection is still present therefore C/A date remains the same 11/14/2022.		
Corrective Action:	Remove stored/ unused equipment	Date:	11/14/2022
Type	OTHER		
Comment:	Random staining from previous inspection around well head still present therefore C/A date remains the same 11/14/2022.		
Corrective Action:	Remove and dispose of properly stained material	Date:	11/14/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 424295 Type: WELL API Number: 081-07666 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover.
 Access road was snow drifted in multiple areas.
 Some areas of location show lack of stabilization which in turn lead to tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: Cloudy Temperature: (F)

Assisting Staff Kris Neidel Camera #: 3

Visible Smoke Referred to CDPHE

Times Surveyed				Equipment Surveyed
Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:15	AM	10:35	AM	Oil Tank(s)
				Separation Equipment
				Wellhead(s)
				Other

Comment: ECD was running with slight heat trace observed with OGI camera.

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403367602	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074707
707800268	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074697
707800269	OIG of production equipment(line heater)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074698
707800270	OGI of ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074699
707800271	OGI of ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074700