

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2023

Submitted Date:

04/06/2023

Document Number:

708200093

**FIELD INSPECTION FORM**Loc ID 310566 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293534	WELL	SI	03/27/2017	ERIW	123-26575	GREEN 1-1	RI
310566	LOCATION	AC			-	Green 1-1	RI

**General Comment:**

This is a follow-up inspection to Field Inspection Report (Doc #708200043) and Operator submitted FIRR (Doc #403347982) to document corrective action compliance.

Inspected Facilities									
Facility ID:	293534	Type:	WELL	API Number:	123-26575	Status:	SI	Insp. Status:	RI
Facility ID:	310566	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. It appears the Operator has addressed the corrective action by installing straw wattles and backfilling areas where rill erosion had occurred. However, during this inspection it was observed that the straw wattles did not appear to be installed per good engineering practices (e.g. trenched in) and an area previously identified has not had any BMPs implemented. Refer to attached inspection photos for documentation.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C.**

Date: 04/10/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403367673	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074829">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074829</a>
708200107	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6074823</a>