

**Operator: EXTRACTION OIL & GAS INC**  
**Location Name: SIMPSON MD-61S69W2NENE**  
**Loc ID: 321379**  
**Inspection: 709400023**



**Exhibit A**

**CA:** Corner post on tank battery perimeter fence has been knocked down, barbed wire fence laying on the ground. See inspection photos. Weeds along access road and north side of location. See inspection photos. Comply with Rule 606 to remove weed debris.

**CA Resolution:** Corner Post has been straightened, and a crew has been scheduled to mow the vegetation along the access road so the location complies with Rule 606.