

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 5122 From entrance to location



Photo # 5123 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 5124 Location




Photo # 5125 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 5126 Meter calibration info not conspicuously posted



Photo # 5127 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 5128 Debris



Photo # 5129 Debris – barbed wire



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136




Photo # 5140 Debris – barbed wire



Photo # 5135 Stained soil & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 138-21 Pad

Location ID: 324136



Photo # 5136 Stained soil & gravel