

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2023

Submitted Date:

04/14/2023

Document Number:

712700009

**FIELD INSPECTION FORM**

Loc ID 313604 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286980	WELL	PR	02/01/2022	CO2	083-06627	YB 5	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo performed a field inspection of the access road and well location.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Locked gate.		
Corrective Action		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	Present
Corrective Action:	
Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Well location is fenced with four strand barb wire and a gate.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 1		
Comment:	Present		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Present		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	1000 GAL	STEEL AST		37.447020,-108.790890
Comment:	Labeled glycol and produced water.				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Skid mounted AST.				
Corrective Action:				Date:

<u>Venting:</u>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<u>Flaring:</u>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 286980 Type: WELL API Number: 083-06627 Status: PR Insp. Status: PR

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Check Dams	Pass			
Compaction	Pass	Culverts	Pass			

Comment: Access road BMPs in place and effective. No erosion or sediment migration observed during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700011	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6082427">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6082427</a>