

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Location



location

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Location



location

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Location



location

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Leaking fitting and stained soil




Leaking fitting and stained soil

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Leaking fitting



Chemical containment is full of fluid

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Lack of stabilization/ compaction



Lack of stabilization/ compaction

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Lack of stabilization/ compaction



Lack of stabilization/ compaction

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Lease road lacks compaction/ stabilization



Access road entrance to location

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Apr 10, 2023 at 12:49:25 PM  
+39.905130,-108.203602 ±4.82r  
COGCC

**Cut slope lacks stabilization/ erosion some still snow covered**



Apr 10, 2023 at 12:48:53 PM  
+39.905209,-108.203751 ±4.75r  
COGCC

**Cut slope lacks stabilization/ erosion**

Caerus Piceance LLC  
PCU 296-6B  
Location # 413466



Cut slope lacks stabilization/ erosion



Cut slope lacks stabilization/ erosion