

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5057 From entrance to location



Photo # 5058 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5059 Location



Photo # 5061 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5062 Debris/Unused equipment



Photo from Inspection 700704636 conducted on 10/25/2022

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5064 Debris/Unused equipment



Photo from Inspection 700704636 conducted on 10/25/2022

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5069 Stained soils & gravel



Photo # 5070 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5072 Lack of stabilization/compaction



Photo # 5073 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5074 Lack of stabilization/compaction



Photo # 5075 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5076 Erosion & transport of sediment onto location



Photo # 5078 Erosion & transport of sediment onto location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 134 Pad

Location ID: 322440



Photo # 5079 Erosion & transport of sediment onto location



Photo # 5094 Meter calibration info not conspicuously posted