

# Inspection Photos

April 10, 2023

Operator: TEP Rocky Mountain- #96850

Location ID: 335447

Location Name: JOLLEY-66S91W/16NWSW

Inspection Document #: 702801460

Garfield County, CO

NWSW Section 16 T6S R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



4/10/23  
+39.527188,-107.566659  
163° S

**Photo 1.** Photo taken from the entrance shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801460



Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



Photo 2. Photos show production areas.





Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 3.** Photos show erosion in the western interim area.





Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 4.** Photos show erosion starting at the western edge of the pad (left) and continuing into the interim area towards a retention pond (right).



Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 5.** Photos show erosion in the western interim area.



Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 6.** Photos show erosion in the western interim area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801460



Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 7.** Photos the cut slope at the southeast is not stabilized.





Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 8.** Photos show the cut slope at the south is not stabilized. The lack of stabilization appears to be impacting vegetation areas above and migrating backwards/upslope as is evidenced by eroded/pedestaled vegetation at the top of the slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801460



Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 9.** Photos show lack of stabilization of the working pad surface leading towards the access road.





Inspection Photos  
Location Name: JOLLEY-66S91W/16NWSW  
Location ID: 335447



**Photo 10.** Photos show an example of interim areas to the east (left) and west (right).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801460