

Inspection Photos
Location Name: Foster 1
API: 05-061-06010



1. Pumping unit with panels installed



2. SE corner of tank battery looking northwest. No visible oil on the ground

Insp #701006844 performed in accordance with Complaint Doc #403372601

Inspection Photos
Location Name: Foster 1
API: 05-061-06010



1. NE corner of tank battery location looking southwest at tank hatches. No visible oil noted on the ground



2. NW corner of tank battery location looking southeast. No oil was on the ground

Insp #701006844 performed in accordance with Complaint Doc #403372601

Inspection Photos
Location Name: Foster 1
API: 05-061-06010



**1. SE corner of tank battery location looking northeast.
No visible oil noted on the ground**



**2. East side of oil and water tanks looking at tank hatches.
No visible oil noted on the ground and no freestanding
fluid was observed**

Insp #701006844 performed in accordance with Complaint Doc #403372601