

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5339 From entrance to location



Photo # 5340 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5341 Location



Photo # 5342 Location

Inspection Photos  
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad  
Location ID: 311536



Photo # 5343 Location



Photo # 5344 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5346 Meter calibration info not conspicuously posted



Photo # 5347 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



**Photo # 5348 Meter calibration info not conspicuously posted**

**Photo # 5349 Meter calibration info not conspicuously posted**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



Photo # 5353 Debris



Photo # 5354 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 113 Pad

Location ID: 311536



**Photo # 5351 Check dams need maintenance**