



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type			
Comment:	See Inspection Doc # 699304236 for related shared facilities and equipment.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	See Inspection Doc # 699304236 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chainlink topped with wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	See Inspection Doc # 699304236 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	partially exposed at surface		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 699304236 for related shared facilities and equipment.				
Corrective Action:		Date:			

<b>Paint</b>	
Condition	<input type="text"/>

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

**Flaring:**

Type			
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

**Inspected Facilities**

Facility ID: 203 Type: WELL API Number: 123-25431 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/13/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 4-17-2023 at approximately 1350 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection:                      Operator: Oxy/Kerr McGee                      Location name: Stromquist 35-21                      API #05-123-25431                      County: Weld                      Weather: Clear.                      Location: Dry.                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection, I observed no compliance issues:                      See attached photos.                      No follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with COGCC rules.</p>	revasr	04/17/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401846	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084191</a>