

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5453 From entrance to location



Photo # 5454 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5455 From entrance to location



Photo # 5461 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5462 Location



Photo # 5463 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5465 Meter calibration info not conspicuously posted



Photo # 5466 Erosion & transport of sediment off location (SE area of location, near entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5467 Erosion & transport of sediment off location/insufficient BMP's (SE area of location, near entrance to location)



Photo # 5469 Erosion & transport of sediment off location/insufficient BMP's (SE area of location, near entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



**Photo # 5471 Erosion & transport of sediment off location
(SE area of location, near entrance to location)**



**Photo # 5474 Transport of sediment off location/choking off
vegetation/insufficient BMP's (SE area of location, near entrance
to location)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5475 Erosion & transport of sediment off location



Photo # 5478 Erosion & transport of sediment off location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5482 Erosion & transport of sediment off location/insufficient BMP's



Photo # 5484 Check dams need maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5486 Check dams need maintenance



Photo # 5493 Retention Pond/BMP's need maintenance (on north side of lease road approximately 1/10th of a mile from location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5494 Rip Rap run needs maintenance (on north side of lease road approximately 1/10th of a mile from location)



Photo # 5497 Ditch needs maintenance/insufficient BMP's/erosion of habitat (on north side of lease road approximately 1/10th of a mile from location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5499 Ditch needs maintenance/insufficient BMP's/erosion of habitat (on north side of lease road approximately 1/10th of a mile from location)

Photo # 5505 Culvert needs maintenance (on spur road into location, approximately 50-75 feet from entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 136-21 Pad

Location ID: 324180



Photo # 5506 Culvert needs maintenance (on spur road into location, approximately 50-75 feet from entrance to location)