

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5397 From entrance to location



Photo # 5398 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5399 Location



Photo # 5400 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5401 Location



Photo # 5402 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5403 Meter calibration info not conspicuously posted



Photo # 5411 Rill erosion (back side of separator units)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5412 Erosion/insufficient BMP's



Photo # 5420 Erosion/insufficient BMP's



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5416 Erosion on slope going into ditch



Photo # 5426 Sediment trap needs maintenance (SW side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5427 Sediment trap needs maintenance (SW side of location)



Photo # 5428 Sediment trap needs maintenance (SW side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5430 Ditch going into sediment trap needs maintenance (SW side of location)



Photo # 5431 Ditch going into sediment trap needs maintenance (SW side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5435 Rill erosion on location



Photo # 5441 Check dams on slope need maintenance (SE side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5442 Check dams on slope need maintenance (SE side of location)



Photo # 5443 Rill erosion/transport of sediment on slope (SE side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5444 Rill erosion/transport of sediment on slope (SE side of location)



Photo # 5448 Ditch & check dams need maintenance (Southern side of location on slope, ditch runs from the SE side of location to the SW side of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 332-21 Pad

Location ID: 335340



Photo # 5449 Ditch needs maintenance (Southern side of location on slope, ditch runs from the SE side of location to the SW side of location)