

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2023

Submitted Date:

04/18/2023

Document Number:

701006855

**FIELD INSPECTION FORM**

Loc ID 336856 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 66190  
Name of Operator: OMIMEX PETROLEUM INC  
Address: 100 CRESCENT COURT, SUITE 700  
City: DALLAS State: TX Zip: 75201

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Robert	(214) 808-4126	rclark@omimexpetroleum.com	
Chambers, Christopher	(214) 549-7215	kchambers@omimexpetroleum.com	
Miller, Wendy	(469) 676-9376	wmiller@omimexpetroleum.com	
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280086	WELL	PR	02/01/2015	GW	125-09499	BLEDSOE 15-19-5-44	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: <a href="#">Dirt road through pasture</a>		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type WELLHEAD		
	Comment: <a href="#">Lease sign by metal shed</a>		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type WELLHEAD		
	Comment: <a href="#">Metal panels around wellhead and metal shed</a>		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
Comment:	<a href="#">2-Gas scrubbers (not in use)</a>		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	<a href="#">Vertical gas separator in metal shed</a>		
Corrective Action:			Date:
Type: Pump Jack	# 0		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	<a href="#">Meter run in metal shed</a>		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 280086 Type: WELL API Number: 125-09499 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well is SI at downstream valve from chart recorder. Casing valve at wellhead is open. Audible leak detected at casing valve on wellhead. Chart shows installation date of 1/9/23. Last production reported was 8/1/22

Corrective Action: Submit reports as per Rule 207.  
Maintain fittings in accordance to rule 608.e

Date: 04/17/2023

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701006884	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084876</a>