

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Access road and county road 72



Access road to location

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Location entrance



Entrance to location view

KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462



API Number missing from tank battery sign

API Number missing from tank battery sign

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Open end tank valve



Label fading and illegible

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Equipment and soil staining



Gas meter calibration cards not visibly displayed

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Lack of stabilization and sediment migration

Erosion and sediment migration

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Erosion and sediment migration

Lack of BMP maintenance

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Northeast corner view



Northwest corner view

**KT Resources LLC
Ant Hill Unit 36-11 & 36-11BD
Location #336462**



Southwest corner view

Southeast corner view