

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5615 From entrance to location



Photo # 5616 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069




Photo # 5617 Stained soils & gravel



Photo # 5618 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5620 Stained soils & gravel



Photo # 5623 Rill erosion & transport of sediment onto location (north side of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5624 Rill erosion & transport of sediment onto location (north side of pad)



Photo # 5625 Rill erosion & transport of sediment onto location (north side of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5627 Rill erosion & transport of sediment onto location (north side of pad)



Photo # 5629 Rill erosion & transport of sediment onto location (north side of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5630 Rill erosion & transport of sediment onto location (north side of pad)



Photo # 5631 Check dams need maintenance (SW area of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5632 Check dams need maintenance (SW area of pad)



Photo # 5633 Check dams need maintenance (SW area of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5634 Rill erosion on the edge of the pad going into the interim area (south side of pad)



Photo # 5635 Rill erosion on the edge of the pad going into the interim area (south side of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 160-22 Pad

Location ID: 335069



Photo # 5648 Debris