

Location

Lease Road:			
Type	Access		
comment:	PHOTO 1: LOCATION NOT ACCESSABLE DO TO TREE FALL ACROSS ROW.		
Corrective Action:	Repair and maintain lease road to comply with rule 204. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.	Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	<input style="width: 100%;" type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date:

Flaring:			
Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date:

Inspected Facilities

Facility ID: 288883 Type: WELL API Number: 071-09160 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695107017, BASED ON PHOTOS SUBMITTED IN FIRR DOC #403335587, CA'S HAVE BEEN ADDRESSED.	beardsit	04/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403372034	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6080022
695107982	ORIG. INSP. PHOTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6080016