

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2023

Submitted Date:

04/07/2023

Document Number:

696304767

**FIELD INSPECTION FORM**Loc ID 430308 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD State: CO Zip: 80111

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430317	WELL	PR	04/08/2013	OW	123-36124	Razor 26-3524H	PR
433963	WELL	PR	10/21/2014	OW	123-37874	Razor 26K-3507A	PR
433964	WELL	PR	10/22/2014	OW	123-37875	Razor 26K-2305A	PR
433965	WELL	PR	10/18/2014	OW	123-37876	Razor 26K-3508B	PR
433966	WELL	PR	09/27/2014	OW	123-37877	Razor 26K-2307A	PR
433967	WELL	PR	09/27/2014	OW	123-37878	Razor 26K-2306B	PR
433968	WELL	PR	09/17/2014	OW	123-37879	Razor 26K-2308B	PR
433969	WELL	PR	12/22/2014	OW	123-37880	Razor 26K-3505A	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Pumping Unit, Daytank, Pollution Pot at Well 26-3524H - See Photos		
Corrective Action:	Comply with Rule 606	Date:	06/09/2023
Type	OTHER		
Comment:	Stained Soil at Pumping Unit and 26-3524H Wellhead - See Photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	04/28/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Pump Jack	# 1		
Comment:	Unused at the Time of this Inspection		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	430317	Type:	WELL	API Number:	123-36124	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433963	Type:	WELL	API Number:	123-37874	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433964	Type:	WELL	API Number:	123-37875	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433965	Type:	WELL	API Number:	123-37876	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433966	Type:	WELL	API Number:	123-37877	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433967	Type:	WELL	API Number:	123-37878	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433968	Type:	WELL	API Number:	123-37879	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433969	Type:	WELL	API Number:	123-37880	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Well 26-3524H - Unused Pumping Unit, Stained Soil at Wellhead and where Gas Engine was removed</a>	petrie	04/07/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403371225	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079304">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079304</a>
696304769	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079302">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6079302</a>