

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5655 From entrance to location



Photo # 5656 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5657 Location



Photo # 5658 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5681 Location



Photo # 5684 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5668 Check dams need maintenance (SW corner of lower pad that wellheads are located on)



Photo # 5669 Check dams need maintenance (SW corner of lower pad that wellheads are located on)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5670 Check dam needs maintenance (SW corner of lower pad that wellheads are located on)



Photo # 5671 Sediment Trap needs maintenance (SW corner of lower pad that wellheads are located on)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5673 Rill erosion & transport of sediment off location (south side of pad)



Photo # 5674 Rill erosion & transport of sediment off location (south side of pad)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad

Location ID: 335175



Photo # 5676 Rill erosion & transport of sediment off location (south side of pad)



Photo # 5679 Meter calibration info not conspicuously posted

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 10-22 Pad
Location ID: 335175



Photo # 5680 Meter calibration info not conspicuously posted

Photo # 5683 Debris