

Inspection Photos

April 17, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324106

Location Name: RU/13-6

Inspection Document #: 702801477

Garfield County, CO

NWSW Section 6 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 1. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 2. Photos show a portable toilet not secured to prevent a spill (left) and unused secondary containment equipment (right).



Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 3. Photo shows a bull plug not installed on a tank drain.



Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 4. Photos show musk thistle rosettes



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 5. Photos show lack of stabilization of the pad surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 6. Photos show interim area slopes at the east are unstabilized.



Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 7. Photos show interim area slopes at the east are unstabilized.



Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 8. Photos show interim area slopes at the north are unstabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 9. Photos show interim area slopes at the west are unstabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 10. Photos show a small portion of the cut at the northeast of the location which leads into a stormwater ditch is unstabilized.



Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 11. Photo shows a sediment trap at the southwest of the location. The interim area above and the side of the trap are not stabilized.



Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 12. Photos show a sediment trap at the northwest of the location. The interim area above and side of the trap is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801477

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 13. Photos show BMPs at the west of the location including erosion of the sediment trap walls.

Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 14. Photos show insufficient sediment trap outlet protections/degraded BMPs.



Inspection Photos
Location Name: RU/13-6
Location ID: 324106



Photo 15. Photos show offsite degradation downslope of the sediment trap outlet pictured in Photo 13.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801477