

**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Access road to location**



**Entrance to location**





**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Containment full of liquid**



**Debris alongside pumping unit**



**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Debris sitting on pumping unit base**



**API Number missing from tank battery sign**

KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347



**Drain valve on loadline lacks cap or plug**



**Gas meter calibration card not visibly displayed**



**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Erosion and sediment migration exiting location**



**Check dams and culvert erosion**



**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Sediment migration onto location**



**Bypass ditch full of sediment, erosion and sediment migration entering location**



**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Erosion and sediment migration leaving location**



**Erosion and sediment migration leaving location**



**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Southwest corner view**



**Northwest corner view**



**KT Resources LLC  
Ant Hill Unit Wyatt 36-13  
Location #316347**



**Northeast corner view**



**Southeast corner view**