

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Apr 19, 2023 at 11:22:08 AM
CO



Apr 19, 2023 at 11:22:11 AM
CO

Photo # 5749 From entrance to location

Photo # 5750 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5751 Location



Photo # 5752 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5753 Location



Photo # 5755 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5756 Open ended load line



Photo # 5758 E & P waste is secondary containment



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5760 E & P waste is secondary containment



Photo # 5759 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5761 Debris



Photo # 5762 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5764 Debris



Photo # 5766 Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5767 Debris



Photo # 5768 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5770 Lack of stabilization/compaction



Photo # 5771 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5772 Lack of stabilization/compaction



Photo # 5776 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5777 Lack of stabilization/compaction



Photo # 5779 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 24-23 Pad

Location ID: 334579



Photo # 5783 Culvert needs maintenance (on lease road near entrance to location)



Photo # 5784 Culvert needs maintenance (on lease road near entrance to location)