

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: 4' barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Prime Mover

1

Comment: electric motor

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: electric

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 239697 Type: WELL API Number: 123-07485 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 01/20/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were windy, overcast, warm.	medinaj	04/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504625	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6088869