

TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location # 335237



Wellheads – Photo #02397



Separators – Photo #02399

TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location # 335237



Tank Battery – Photo #02404

Inadequate Berm Capacity - Photo #02406

TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location # 335237



Rill Erosion/Transport of Sediment from Location – Photo #02401

Lack of Stabilization – Photo #02407

TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location # 335237



**Inadequate Vehicle Tracking BMPs at Location
Entrance/Exit – Photo #02409**

Access Road Ditch Erosion– Photo #02395