

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2023

Submitted Date:

04/20/2023

Document Number:

708300322

FIELD INSPECTION FORMLoc ID 335353 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256943	WELL	PR	07/06/2000	GW	045-07503	UNOCAL GM 223-33	PR
260632	WELL	PR	01/01/2018	GW	045-07888	UNOCAL GM 444-33	PR

General Comment:**COGCC Inspection Report Summary**

On 4/20/2023 at approximately 12:15, Compliance Inspector Matthew Morris conducted an follow-up inspection at TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESE at Location ID #335353 in Garfield County, Colorado.

Normal production operations were observed.

Corrective action from FIR #699805231 has been completed.

During the inspection, the following compliance issues were observed:

- 1) Gas meter calibration record not conspicuously posted
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 4	
Comment:	Gas meter calibration record not conspicuously posted	
Corrective Action:	Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2)	Date: 04/30/2023
Type: Plunger Lift	# 2	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible.	
Corrective Action:		Date:
Type: Bird Protectors	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	256943	Type:	WELL	API Number:	045-07503	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing							
Corrective Action:						Date:			
Facility ID:	260632	Type:	WELL	API Number:	045-07888	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		Producing							
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail			Inadequate vehicle tracking BMPs
Berms						
Other	Fail					Inadequate vehicle tracking BMPs
		Compaction				
		Gravel				
Gravel						
		Ditches				
Compaction						

Comment: [Inadequate vehicle tracking BMPs in place to minimize the transportation of sediment from location and lease road](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations to comply with Rule 1002](#)

Date: 05/05/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300328	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6089150