

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2023

Submitted Date:

04/13/2023

Document Number:

707800290

FIELD INSPECTION FORMLoc ID 316207 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Anthony	303-886-8733	tony@kt-res.com	
Baumgras, Dan		dan@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257080	WELL	PR	08/01/2022	GW	103-10006	WRD UNIT 29-21	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 4/11/2023, I, Inspector Scott Ramsey, conducted a routine inspection at KT Resources Ward Unit 29-21, at Location # 316207 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed shut in well. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

During this inspection the following compliance issues were observed:

1. Some areas of location show signs of lack of stabilization which in turn can lead to tracking issues.
 2. Access road shows signs of lack of stabilization
 3. No BMP's installed to prevent sediment migration from occurring on location.
 4. No API posted on well head or battery signage.
 5. Chemical and oil tank containment full of fluid not sufficient to contain possible spill.
 6. Chemical tank label is illegible
 7. Meter calibration card not conspicuously posted.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank label is illegible		
Corrective Action:	Provide proper labeling	Date:	05/04/2023
Type	BATTERY		
Comment:	No API posted on well head or battery signage.		
Corrective Action:	Provide proper signage	Date:	05/04/2023
Type	WELLHEAD		
Comment:	No API posted on well head or battery signage. See battery for C/A.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-288-0560

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Chemical and oil tank containment full of fluid not sufficient to contain possible spill.		
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill	Date:	05/04/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter calibration card not conspicuously posted.		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration.	Date:	05/04/2023
Type: Ancillary equipment	# 2		

Comment:		Chemical tank in plastic containment		Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:		Not lined		
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:		not lined		
Corrective Action:		Date:		

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 257080	Type: WELL	API Number: 103-10006	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
Compaction	Fail					

Comment: 1. Some areas of location show signs of lack of stabilization which in turn can lead to tracking issues.
 2. Access road shows signs of lack of stabilization
 3. No BMP's installed to prevent sediment migration from occurring on location.

Corrective Action: **Install or repair required BMPs**

Date: 05/25/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403374569	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6082572
707800302	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6082559