

**Caerus Piceance LLC
RNP 197-15A1
Location #441601**



Access at county road



Access to location

**Caerus Piceance LLC
RNP 197-15A1
Location #441601**



Entrance to location



Debris

Caerus Piceance LLC
RNP 197-15A1
Location #441601



Random debris



Trash

**Caerus Piceance LLC
RNP 197-15A1
Location #441601**



Unused equipment?



Unused equipment?

Caerus Piceance LLC
RNPU 197-15A1
Location #441601



Section numbers do not match



Section numbers do not match



Caerus Piceance LLC
RNP 197-15A1
Location #441601



Debris




Debris

Caerus Piceance LLC
RNPU 197-15A1
Location #441601



Debris



Debris



**Caerus Piceance LLC
RNPU 197-15A1
Location #441601**



Debris



Open end valve on loadline

Caerus Piceance LLC
RNP 197-15A1
Location #441601



Debris



Debris

Caerus Piceance LLC
RNP 197-15A1
Location #441601



Debris



Debris

Caerus Piceance LLC
RNPU 197-15A1
Location #441601



Debris



Staining

Caerus Piceance LLC
RNP 197-15A1
Location #441601



Debris



Debris



Caerus Piceance LLC
RNP 197-15A1
Location #441601



Conflicting labels



Last gas meter calibration date not posted

**Caerus Piceance LLC
RNP 197-15A1
Location #441601**



Unstable slope. Soil migration. Debris.



Unstable slope. Soil migration. Debris.

**Caerus Piceance LLC
RNP 197-15A1
Location #441601**



Northwest corner photo



Southwest corner photo

**Caerus Piceance LLC
RNPU 197-15A1
Location #441601**



Southeast corner photo



Northeast corner photo