

# Inspection Photos

Loc: 325172

Operator: LOGOS OPERATING LLC

Inspection Date: 4/18/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Loc:325172 | Date: 4/18/2023

## Inspection Photos



**Photo 1.** Facing southeast toward the well site at red arrow. The wellsite is located within an oxbow of the Florida River. The river is flowing very high from runoff and there is potential for flooding that could occur at the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023

## Inspection Photos



**Photo 2.** Facing southeast toward the location and production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023



## Inspection Photos



**Photo 3.** Facing toward the open top tank. There is round rock placed around the containment which will not prevent flood water from entering underneath the steel containment. The steel containment is not constructed per the Operator's SWMP. Previous corrective action has not been completed.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Loc:325172 | Date: 4/18/2023



## Inspection Photos



**Photo 4.** The steel containment is no constructed per the Operator's SWMP. A 3.5 ft. shovel was placed at the containment for scale.



**Photo 5.** The steel containment is only about 4 inches below grade. The steel containment is not constructed per the Operator's SWMP.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023



## Inspection Photos



**Photo 6.** Facing toward the open top tank with produced fluids.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023



## Inspection Photos



**Photo 7.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023



## Inspection Photos



**Photo 8.** Facing southeast toward the location. The area of the road shows signs of scouring where flood flows across the road from left to right towards the Florida River.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023



## Inspection Photos



**Photo 9.** Facing southeast toward the location. The area of the road shows signs of scouring where flood flows across the road from left to right towards the Florida River.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:325172 | Date: 4/18/2023