

# Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 331251

Inspection Document #: 697504606

Weld County, CO

NENW Section 28 T5N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DOW #21-28  
Location ID: 331251



**Photo 1.** COGCC GISOnline aerial imagery from 2021. This inspection covers the well location, access road and tank battery.



Inspection Photos  
Location Name: DOW #21-28  
Location ID: 331251



**Photo 2.** Photo taken from the well location, facing North. Photo illustrates the location consists mostly of weeds with little to no perennial vegetation that is not reflective of reference areas.



**Photo 3.** Photo taken from the well location, facing West. See comments under Photo 2.



Inspection Photos  
Location Name: DOW #21-28  
Location ID: 331251



**Photo 4.** Reference photo taken adjacent to the well location, facing North.



Inspection Photos  
Location Name: DOW #21-28  
Location ID: 331251



**Photo 5.** Photo taken along a section of the access road, facing East. Photo illustrates weedy establishment and weed debris growing along the access road.



**Photo 6.** Photo taken along a section of the access road, facing West. See comments under Photo 5.





**Photo 7.** Photo taken from a portion of the access road. COGCC staff dug ~5-6" down and hit a refusal area of gravel. It does not appear the Operator removed all the gravel from the access road. This was not observed in reference areas. Refer to Photo 8.



**Photo 8.** Photo taken adjacent to the previous Photo #7 within reference areas. COGCC staff was able to dig ~8" down without encountering any rock.



Inspection Photos  
Location Name: DOW #21-28  
Location ID: 331251



**Photo 9.** Photo taken from the offsite tank battery location, facing South. Photo illustrates what appears to be unused midstream equipment. Operator shall coordinate with the midstream Operator to get this removed.



**Photo 10.** Photo taken from the offsite tank battery location, facing North. See comments under Photo 9.



Inspection Photos  
Location Name: DOW #21-28  
Location ID: 331251



**Photo 11.** Photo taken from the offsite tank battery location, facing East. Photo illustrates the location consists mostly of weeds with some perennial vegetation that is reflective of reference areas.

Note- noxious weeds, Scotch thistle, were observed on and off the location, and the Operator shall manage the weeds on their location.



**Photo 12.** Photo taken from the offsite tank battery location, facing North. See comments under Photo 11.