

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5841 From entrance to location



Photo # 5842 From entrance to location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5843 Location



Photo # 5844 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913




Photo # 5845 Location



Photo # 5846 Containment liner needs maintenance



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5849 Containment liner needs maintenance



Photo # 5852 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5889 Open cellar – Wildlife Hazard (Approximately 50 yards south of location)



Photo # 5853 Erosion & transport of sediment off location (North side of pad on slope near production tank)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



**Photo # 5854 Erosion & transport of sediment off location
(North side of pad on slope near production tank)**



**Photo # 5856 Erosion & transport of sediment off location
(West side of pad on slope near production tank)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



**Photo # 5857 Erosion & transport of sediment off location
(West side of pad on slope near production tank)**



**Photo # 5862 Erosion & transport of sediment off location
(West side of pad on slope near production tank)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



**Photo # 5864 Erosion & transport of sediment off location
(West side of pad on slope near production tank)**



**Photo # 5865 Erosion & transport of sediment (North side of
pad on slope near production tank)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5873 Erosion & transport of sediment down spur road



Photo # 5874 Erosion & transport of sediment down spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5875 Erosion & transport of sediment down spur road



Photo # 5876 Erosion & transport of sediment down spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5877 Erosion/transport of sediment down spur road & transport of sediment off of spur road into a vegetated area/insufficient BMP's



Photo # 5887 Erosion/transport of sediment down spur road & transport of sediment off of spur road & into a vegetated area/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5878 Erosion/transport of sediment down spur road & transport of sediment off of spur road into a vegetated area/insufficient BMP's



Photo # 5879 Erosion/transport of sediment down spur road & transport of sediment off of spur road into a vegetated area/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5880 Erosion/transport of sediment down spur road & transport of sediment off of spur road into a vegetated area/insufficient BMP's



Photo # 5881 Erosion/transport of sediment down spur road & transport of sediment off of spur road into a vegetated area/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5882 Erosion/Transport of sediment off of spur road into a vegetated area/insufficient BMP's



Photo # 5883 Erosion/Transport of sediment off of spur road into a vegetated area/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 34-28 Pad

Location ID: 323913



Photo # 5884 BMP's need maintenance (North side of spur road near culvert & rip rap run approximately 10-20 yards down spur road)