

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2023

Submitted Date:

04/17/2023

Document Number:

702401842

**FIELD INSPECTION FORM**Loc ID 333138 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240805	WELL	SI	01/01/2023	OW	123-08593	RASMUSSEN 1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type			
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	unused pump jack broken down on location		
Corrective Action:	Comply with Rule 606 unused equipment	Date:	05/17/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type:	#		
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	partially exposed at surface		
Corrective Action:		Date:	

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	unused		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	See Inspection Doc # 702400616 for related shared facilities and equipment.					
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 240805 Type: WELL API Number: 123-08593 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 05/11/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 4-17-2023 at approximately 1315 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location name: Rasmussen 1</p> <p>API #05-123-08593</p> <p>County: Weld</p> <p>Weather: Clear.</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite, SI at the time of inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>606 unused Equipment: unused pump jack on location, CA date 5-17-2023.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	04/17/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403375898	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084203">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084203</a>
702401843	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084190">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084190</a>