

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location # 335390



Location Entrance – Photo #02468



Wellheads – Photo #02472

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location # 335390



Separators – Photo #02471



Berm Liner Damaged – Photo #02469

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location # 335390



Water Accumulation – Photo #02474



Lack of Stabilization – Photo #02475

CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location # 335390



Inadequate Vehicle Tracking BMP at Location Entrance – Photo #02473



Access Road Degradation/Transportation of Sediment – Photo #02493



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources