

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2023

Submitted Date:

04/24/2023

Document Number:

708900343

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 323926 _____ Smelser, Wayne _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 9 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211243	WELL	PR	01/14/1996	GW	045-07002	FEDERAL RMV 59-17	PR

General Comment:**COGCC Inspection Report Summary**

On 04/24/2023 at approximately 10:48 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC RMV 59-17 pad.
 Location # 323926 in Garfield County Colorado.
 Location is within High Priority/Density Habitat areas.
 While there, I observed normal production operations.

This is a summary of inspection report.

This location/well is located inside of the Garfield County Landfill

Remote location/split pad - Wellhead only, production equipment for this well is located at the DOE 9-17MV pad/production facility, location # 335134

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Taylor plug on bradenhead, bradenhead valve is accessible		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 211243 Type: WELL API Number: 045-07002 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well is on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Gravel				Sparse
		Culverts				
		Ditches				
		Compaction				
Compaction						

Comment: Well pad is inside the Garfield County Landfill, no other observed BMP's on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
This location/well is located inside of the Garfield County Landfill	smelserw	04/24/2023
Remote location/split pad - Wellhead only, production equipment for this well is located at the DOE 9-17MV pad/production facility, location # 335134		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900344	Inspection 708900343 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6092139