

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2023

Submitted Date:

04/18/2023

Document Number:

696204839

## FIELD INSPECTION FORM

 Loc ID 334431 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Findings:**

- 15 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334431	LOCATION	AC			-	Reppo B Pad	RI
412664	WELL	PR	12/01/2022	GW	045-18530	REPP0 34-14A	RI
412665	WELL	PR	10/01/2019	GW	045-18529	REPP0 34-15B	RI
412666	WELL	PR	10/01/2019	GW	045-18531	REPP0 34-14D	RI

**General Comment:**

On 4/17/2023, Reclamation Specialist Trujillo inspected TEP Rocky Mountain's Reppo B Pad location in Garfield County, Colorado.

This is also a follow-up inspection to #696204522, to document compliance for the following corrective actions:

- Interim Reclamation
- Undesirable Plant Species
- Liner integrity

It was observed in this inspection that the Corrective Actions have been taken, or are "in process".

The following new compliance issues were observed during this inspection:

- Signage

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Signage at battery not posted		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/18/2023
Type	OTHER		
Comment:	Location Entrance		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-285-9377/911		
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog Panelling		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog Panelling		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 334431 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 412664 Type: WELL API Number: 045-18530 Status: PR Insp. Status: RI

Facility ID: 412665 Type: WELL API Number: 045-18529 Status: PR Insp. Status: RI

Facility ID: 412666 Type: WELL API Number: 045-18531 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ In Process \_\_\_\_\_

Comment [Soils on the interim areas, slopes and stockpiles on the Location appear to have been hydromulched/seeded; unclear if northern areas have also been mulched. Continue to monitor/maintain BMPs until long-term stabilization has been achieved.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_ In \_\_\_\_\_

Comment [Materials utilized during interim reclamation activities observed on Location.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ In \_\_\_\_\_

Comment [Equipment utilized during interim reclamation activities observed on Location.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment [Anchors not observed.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_



<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening						
		Other				Water Bar, Location entrance
Gravel		Gravel				
Hydro Mulch						
Comment: <input type="text" value="See 'COGCC Comments'."/>						Date: _____
Corrective Action: <input type="text"/>						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>RECLAMATION COMMENT</b></p> <p>Inspection #696204522 observed that interim reclamation of areas not needed for production operations have not been performed.</p> <p>Inspection also observed Undesirable Plant Species on the Location. Inspection required Operator to comply with 1003 rules.</p> <p>It was observed in this inspection that interim reclamation activities appeared to be in process- areas not needed for production have been recontoured. Compaction alleviation appears to have been performed in one direction; unclear at time of inspection if areas were cross-ripped. Operator appears to have hydromulched/seeded most of the interim areas, as well as remaining soil stockpiles; unclear at time of inspection if mulching activities have been completed on northern interim areas.</p> <p>A followup inspection will be conducted to determine compliance with Rules 1002.f/1002.c, as well as Rules 606.c/1003.f</p> <p>Interim Reclamation "in process".</p>	trujilloam	04/18/2023
<p><b>STORMWATER COMMENT</b></p> <p>Location does not appear to have been constructed with an engineered outlet to mitigate ponding on site, and to allow for stormwater to discharge from the working pad areas in such a manner that minimizes erosion, degradation and off-site sediment transport- ponding on north end of the Location observed, unclear if this is stormwater, or related to hydromulching activities. Stormwater ponding can contribute to the destabilization of the working pad surface; inadequate runoff protections can result in erosion, degradation and sediment transport to the working pad, the interim, and/or other off-site areas.</p> <p>Review of SW BMPs on Location advised.</p> <p>Continue to monitor/manage stormwater on the Location; ensure BMPs remain adequate for the site's conditions, and in proper functioning condition in accordance with good engineering practices.</p>	trujilloam	04/18/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403376331	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084822</a>

696204840	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6084820</a>
-----------	-------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------