

Inspection Photos

4/24/2023

Operator: WINDSOR ENERGY GROUP LLC -
10081

Location #315696
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 1: Photos taken from the northern access road. Photo shows Final Reclamation activities, including but not limited to, removal of road base/gravel, compaction alleviation, recontouring/regrading and reclamation has not been completed.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 2: Undesirable Plant Species (Halogeton) from the previous growing season observed on Location. Weed management is not occurring; weed germination observed.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 3: Photos taken from the northern access road. Photo shows stormwater and erosion control BMPs remain missing or insufficient on the Location and access road. Erosion degradation has persisted.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 4: Photos examples showing various trash debris and pipe equipment observed along access road, and Location.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



April 24, 2023



April 24, 2023

Photo 5: Photos 5-6 taken from the east end of the well site. Photos provide an overview from south, southwest, northwest to north. Final reclamation activities, including but not limited to, removal of road base/gravel, compaction alleviation, recontouring/regrading and reclamation has not been completed.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 6: See comments under photo 5. Yellow arrow shows apparent cuts; Location has not been properly contoured.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 7: Photo shows area where the northern access road meets the Location. Photo shows sediment deposition due to erosion degradation and runoff from the access road.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 8: Photos taken from the southern access road. Photo shows stormwater and erosion control BMPs remain missing or insufficient on the Location and access road. Erosion degradation has persisted. Photos also show Final Reclamation activities, including but not limited to, removal of road base/gravel, compaction alleviation, recontouring/regrading and reclamation has not been completed.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 9: Trash debris remaining along southern access road.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 10: Photos taken from the southern access road. Photo shows Final Reclamation activities, including but not limited to, removal of road base/gravel, compaction alleviation, recontouring/regrading and reclamation has not been completed.

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location #315696



Photo 11: Google earth aerial imagery and overview of the Location and access road(s).