


Scout Energy LLC Associated Unit A 2X Location #316438



Access and location from lease road



Access to location entrance

**Scout Energy LLC
Associated Unit A 2X
Location #316438**



Entrance to location




Lack of stabilization

**Scout Energy LLC
Associated Unit A 2X
Location #316438**



Wellhead equipment



Surface casing to flowline

**Scout Energy LLC
Associated Unit A 2X
Location #316438**



Erosion and sediment migration



Erosion and sediment migration

**Scout Energy LLC
Associated Unit A 2X
Location #316438**



Lack of stabilization



Sediment movement

**Scout Energy LLC
Associated Unit A 2X
Location #316438**



Southeast corner of location



Northeast corner of location

**Scout Energy LLC
Associated Unit A 2X
Location #316438**



Northwest corner of location



Southwest corner of location