

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 6239 From entrance to location

Photo # 6240 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 6241 Location



Photo # 6242 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 6243 Tank label inaccurate/incorrect information

Photo # 6244 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456




Photo # 6245 Meter calibration info not conspicuously posted



Photo # 6262 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 6246 Debris



Photo # 6247 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF CLOUGH 19 Pad

Location ID: 322456



Photo # 6253 Chemical containment is approximately 3/4 full/Failure to maintain chemical BMP



Photo # 6346 Open cellar/wildlife hazard (Cellar is on lease road approximately 1/10 of a mile from entrance to location)