



**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused concrete slab where pump jack would be placed, unused transformers and meter box		
Corrective Action:	Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements.		Date: 10/28/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	unused ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:			Date:

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	meter box and transformers (unused)		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV CONCRETE		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.110510,-104.835860
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Wells Served By Facilities Above**

API Number
123-08728

**AirsID**

API Number	AirsID
------------	--------

123-09014

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240940 Type: WELL API Number: 123-08728 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 02/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 4/25/2023 at approximately 1320 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up inspection to Doc # 699304331 &amp; 702400097. Operator: KP Kauffman                      Location: 1415 Corp. Unit E #1                      API #05-123-08728                      County: Weld.                      While there, I observed a wellsite and tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed and are delinquent:                      606 housekeeping: Unused concrete slab where pump jack would be placed, unused transformers and meter box, CA date 10-28-2021.                      See attached photos.                      Location: dry, Weather: cloudy.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	04/25/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401889	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093447">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093447</a>