

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6351 From entrance to location



Photo # 6352 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6353 Berm needs maintenance/erosion & transport of sediment (E/NE area of berm)



Photo # 6354 Berm needs maintenance/erosion & transport of sediment (E/NE area of berm)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6355 Erosion & transport of sediment on location (E/NE area of location)



Photo # 6357 Erosion & transport of sediment on location (E/NE area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6364 Sediment trap & Rip Rap need maintenance

Photo # 6368 Check dams need maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6372 Check dams need maintenance



Photo # 6373 Rip Rap run needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6374 Ditch & Rip Rap need maintenance (near culvert at entrance to location)



Photo # 6375 Ditch & Rip Rap need maintenance (near culvert at entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6376 Rip Rap needs maintenance (near culvert at entrance to location)



Photo # 6377 Rip Rap needs maintenance (near culvert at entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6378 Rip Rap needs maintenance (near culvert at entrance to location)



Photo # 6379 Rip Rap needs maintenance (near culvert at entrance to location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6385 Erosion on slope of ditch near Rip Rap



Photo # 6386 Erosion in multiple spots on slope of ditch

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6387 Erosion on slope going into ditch



Photo # 6389 Erosion & transport of sediment on slope just off location (S/SW area)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6390 Erosion & transport of sediment on slope just off location (S/SW area)



Photo # 6391 Erosion & transport of sediment on slope just off location (S/SW area)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6393 Erosion & transport of sediment on slope just off location (S/SW area)



Photo 6149 Erosion & transport of sediment on edge of location (S/SE area of location)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 313-16 Pad

Location ID: 335453



Photo # 6399 Erosion & transport of sediment on edge of location (S/SE area of location)