

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6058 From entrance to location



Photo # 6059 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Apr 24, 2023 at 8:57:13 AM
CO



Apr 24, 2023 at 8:57:17 AM
CO

Photo # 6060 Location

Photo # 6061 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6062 Location



Photo # 6063 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6064 Location



Photo # 6065 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6066 Location



Photo # 6072 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6074 Stained soils



Photo # 6075 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6080 Failure to minimize surface disturbance



Photo # 6081 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6083 Failure to minimize surface disturbance



Photo # 6086 Failure to minimize surface disturbance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6087 Failure to minimize surface disturbance



Photo # 6088 Lack of stabilization/Compaction/Insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6089 Lack of stabilization/Compaction/Insufficient tracking BMP's



Photo # 6090 Lack of stabilization/Compaction/Insufficient tracking BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6094 Lack of stabilization/Compaction/Insufficient tracking BMP's



Photo # 6097 Lack of stabilization/Compaction on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6098 Lack of stabilization/Compaction on location

Photo # 6102 Lack of stabilization/Compaction on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6103 Lack of stabilization/Compaction on location



Photo # 6104 Lack of stabilization/Compaction on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6105 Lack of stabilization/Compaction on location



Photo # 6107 Lack of stabilization/Compaction on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LANGSTAFF 1 Pad

Location ID: 335194



Photo # 6108 Lack of stabilization/Compaction on location



Photo # 6067 Meter calibration info not conspicuously posted