

Inspection Photos

Loc: 393275

Operator: FOUR CORNERS ENERGY LLC

Inspection Date: 4/19/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc:393275 | Date: 4/19/2023

Inspection Photos



Photo 1. Facing southwest at the location which was recontoured however there are areas that have not re-established a perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:393275 | Date: 4/19/2023

Inspection Photos



Photo 2. Facing south at the location. There are areas of noxious weeds that need to be controlled. Red arrow points to Mullein and thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:393275 | Date: 4/19/2023

Inspection Photos



Photo 3. Facing south at the location. Numerous pine trees are growing back throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:393275 | Date: 4/19/2023

Inspection Photos



Photo 4. Facing back to the north. There are areas that have not re-established a perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:393275 | Date: 4/19/2023