

Inspection Photos

4/24/2023

Operator: SCOUT ENERGY MANAGEMENT LLC
- 10779

Location #398964
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location #398964



Photo 1: Photos 1-2 taken from the north end of the reclamation area (reclamation work includes both the McLaughlin 67 and 68 Locations). Photos provide an overview of the Location(s) from east, southeast, southwest to west. Vegetation observed in the photos are predominantly Undesirable Plant Species (Halogeton). Desirable plant germination/establishment not apparent.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location #398964



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location #398964



Photo 3: Photos show reclamation areas of the former access road. Vegetation observed in the photos are predominantly Undesirable Plant Species (Halogeton). Desirable plant germination/establishment not apparent.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779

Location #398964



Photo 4: Reclaimed Location surface. Vegetation observed in the are predominantly Undesirable Plant Species (Halogeton). Desirable plant germination/establishment not apparent.