

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2023

Submitted Date:

04/26/2023

Document Number:

696204876

FIELD INSPECTION FORMLoc ID 398964 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		RangelyRegulatory@scoutep.com	Rangely Field
Johnson, Mike		Mike.Johnson@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199946	WELL	PA	08/30/2019	LO	103-40196	MCLAUGHLIN 67	RI
398964	LOCATION	AL			-	MCLAUGHLIN-61N102W 5NENE	RI

General Comment:

On 4/24/2023 Reclamation Specialist Trujillo conducted a final reclamation inspection at the McLaughlin 67 Location in Rio Blanco, County, Colorado

The following compliance issues were observed during this inspection:

-606.c / 1004.e- Undesirable Plant Establishment

-1004- Final reclamation

Refer to the "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	199946	Type:	WELL	API Number:	103-40196	Status:	PA	Insp. Status:	RI
Facility ID:	398964	Type:	LOCATION	API Number:	-	Status:	AL	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Pass

Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured Pass

Compaction alleviation Pass Dust and erosion control In

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Fail Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [See "COGCC Comments".](#)

Corrective Action: _____ Date **06/30/2023**

Comply with Rules 606.c and 1004.e, and conduct weed management on the Location/Access Road; continue to monitor and manage weeds to ensure Location/Road is kept free of all Undesirable Plant Species.

Comply with Rule 1004.d and conduct additional reclamation efforts on the Location/Access Road; continue to monitor and manage the reclamation to ensure site progresses towards a uniform, desirable perennial vegetative cover of at least 80% of the adjacent, undisturbed reference areas.

Overall Final Reclamation

FailWell Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment	User	Date
RECLAMATION COMMENTS	trujilloam	04/26/2023
Form 6(s) #402181110 shows well was Cut/Capped by Whiting O&G Corp on 8/30/2019; Scout Energy Management became Operator for Location/Well effective 7/15/2022.		
Pursuant to Form 27(s) #402267551, reclamation commenced 5/1/2020.		
It was observed in this inspection that final reclamation work has been performed on the Location and access road; areas appear to have been recontoured, revegetation activities conducted, and soils mulched; reclamation work appears to have also included the McLaughlin 68 well site. At least 3 growing seasons have passed; it was also observed that the reclamation areas are predominantly an Undesirable Plant Species (Halogeton) monoculture; desirable plant germination and establishment was not apparent. Reclamation and weed management efforts insufficient; additional revegetation efforts required.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204877	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094446