

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2023

Submitted Date:

04/26/2023

Document Number:

697602064

FIELD INSPECTION FORM

Loc ID 332731 Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249111	WELL	SI	09/01/2022	OW	123-16913	FEDERAL 11-10	EI
273615	WELL	SI	02/01/2023	GW	123-22386	ARISTOCRAT ANGUS FEDERAL 2-10	EI
273715	WELL	TA	02/01/2023	GW	123-22396	ARISTOCRAT ANGUS FEDERAL 1-2-10	EI
280927	WELL	AL	05/27/2009	LO	123-23331	ARISTOCRAT ANGUS FEDERAL 1-1-10	EI
473113	OFF-LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 10NWNW	EI
473114	OFF-LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 10NWNW	EI
473115	OFF-LOCATION FLOWLINE	AC	03/31/2021		-	Wellhead Line 10NWNW	EI
483702	SPILL OR RELEASE	CL	03/22/2023		-	Aristocrat Angus Federal 2-10	EI

General Comment:

This is an Environmental inspection. Any corrective actions from previous inspections or forms that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos are attached to document site conditions.

Historical impacts were discovered during maintenance activities at the Aristocrat Angus Federal 2-10 tank battery. The above ground oil tank was removed, and impacted soil was discovered. Excavation is currently underway.

Location

Overall Good:

Emergency Contact Number:

Comment: Good.

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Metal fencing is adequate		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Orange construction fencing around the excavation is adequate.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fencing is adequate.		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 1		corrective date
Comment:	Good.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 2		
Comment:	Good		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER					
Comment:	Removed from location.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment: Berm looks to have contained the spill.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment: Good.					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: <u>249111</u>	Type: <u>WELL</u>	API Number: <u>123-16913</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>273615</u>	Type: <u>WELL</u>	API Number: <u>123-22386</u>	Status: <u>SI</u>	Insp. Status: <u>EI</u>
Facility ID: <u>273715</u>	Type: <u>WELL</u>	API Number: <u>123-22396</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>280927</u>	Type: <u>WELL</u>	API Number: <u>123-23331</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>473113</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>473114</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>473115</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>483702</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil		Adequate		
Comment	Oily soil stockpile is still onsite next to the excavation.			
Corrective Action				Date:

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602065	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094452