

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2023

Submitted Date:

04/26/2023

Document Number:

705000282**FIELD INSPECTION FORM**Loc ID 426666 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426663	WELL	SI	01/01/2022	GW	123-34755	LUDWIG H 06-31D	TA
426666	LOCATION	AC			-	LUDWIG H 06-31D	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 426663 Type: WELL API Number: 123-34755 Status: SI Insp. Status: TA

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Ludwig H 06-31D) is Temporarily Abandoned; fenced excavations observed at WH and facility/ battery. The WH flowline has been removed. No flowlines/ risers observed at excavation areas at WH or facility. The facility/ tank battery (327825) is decommissioned; tanks and equipment removed. Excavation/ remediation work is in progress.

Corrective Action:

Date:

Facility ID: 426666 Type: LOCATION API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000283	Signage at TA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094557
705000284	Excavation at TA well; FL removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094558