

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6301 From entrance to location



Photo # 6302 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6303 Location



Photo # 6304 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6305 Location



Photo # 6310 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6311 Meter calibration info not conspicuously posted



Photo # 6312 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6313 Lack of stabilization/compaction



Photo # 6314 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6316 Lack of stabilization/compaction



Photo # 6317 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6318 Lack of stabilization/compaction



Photo # 6333 Lack of stabilization/compaction

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6334 Lack of stabilization/compaction



Photo # 6321 Erosion & transport of sediment off location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6323 Erosion & transport of sediment off location



Photo # 6324 Erosion & transport of sediment off location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6327 Erosion & transport of sediment off location

Photo # 6328 Erosion & transport of sediment off location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6329 Erosion & transport of sediment off location



Photo # 6330 Erosion & transport of sediment off location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 135 Pad

Location ID: 322438



Photo # 6335 Erosion & transport of sediment off location



Photo # 6336 Erosion & transport of sediment off location