

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278



Photo #1. Overview of well location.

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278



Photo #2. Wellhead spill and impacted material.

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278



Photo #3. Wellhead spill and impacted material.

Inspection Photos
Petrox Candelaria 33-5 #10-1
API 007-06278



Photo #4. Wellhead sign with incorrect API number.

