

Inspection Photos
Location Name: Raindance FC 20-362HNX
API #: 05-123-44987



Photo 1: Wellhead Sign




Photo 2: Wellhead, previous operator signage

Inspection Photos
Location Name: Raindance FC 20-362HNX
API #: 05-123-44987



Photo 3: Stained soil, unused/disconnected equipment