

Inspection Photos

Location Name: Raindance FD 20-319 HNX

API #: 05-123-44990



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Raindance FD 20-319 HNX
API #: 05-123-44990




Photo 3: Debris (birds nest)



Photo 4: Previous operator signage