

Inspection Photos

Loc: 322108

Operator: FOUR CORNERS ENERGY LLC

Inspection Date: 4/19/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 1. Facing west along the access road. There is a cattleguard that is filled in with sediment and has not been removed. There is also another cattleguard further down the road that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 2. Facing west along the access road. There are culverts along the road that are filled in with sediment. Red arrow shows culvert filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 3. Further west down the road there is exposed flowline shown at red arrow from erosion cutting a deep channel into the road side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 4. Further west down the road there is exposed flowline shown at red arrow from erosion cutting a deep channel into the road side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 5. Facing west along the road. The road side is being washed out in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 6. Facing northeast along the access road which goes into the canyon towards the wellsite location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 7. Facing northeast toward the wellsite. PA marker is shown at red arrow. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 8. Drone aerial photo facing northeast toward the wellsite location.



Photo 9. Drone aerial photo facing southwest showing the access road which leads and ends at the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 10. West side of the location facing southeast.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos




Photo 11. North corner of the location facing southwest. There are four guyline anchors that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 12. There is an above ground PA marker at the location. There is a small 2" pipe shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 13. Facing toward the southeast cut slope. There is a bermed area where tanks were location and pipe risers flowline still remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 14. View of 3 pipe risers and 12' plate.



Photo 15. View of above ground flow line which goes up the hill towards the Federal 2-19 wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 16. Standing at the top of the cut slope facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023

Inspection Photos



Photo 17. South side of the cut slope facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322108 | Date: 4/19/2023